

Figure 1: Long section view of infill drilling (facing west) – highlight drill intercepts

¹These intercepts were not plotted in Figure 1 of the Rubicon news release dated September 25, 2014, but are included to demonstrate continuity of mineralization







Figure 2: Plan view of infill drilling – highlight drill intercepts

Figure 3: Cross section of infill drilling, south to north sequence, 49800N to 50300N




Section 49825N (facing north)







PR15-1 For more information, contact Allan Candelario, CFA, Vice President of Investor Relations Phone: 1.866.365.4706 | E-mail: ir@rubiconminerals.com | www.rubiconminerals.com Rubicon Minerals Corporation | Suite 400–44 Victoria St. | Toronto, ON, CANADA M5C 1Y2 The Toronto Stock Exchange has not reviewed and does not accept responsibility for the adequacy or accuracy of this release



PR15-1 For more information, contact Allan Candelario, CFA, Vice President of Investor Relations Phone: 1.866.365.4706 | E-mail: ir@rubiconminerals.com | www.rubiconminerals.com Rubicon Minerals Corporation | Suite 400–44 Victoria St. | Toronto, ON, CANADA M5C 1Y2 The Toronto Stock Exchange has not reviewed and does not accept responsibility for the adequacy or accuracy of this release





Section 50300N (facing north)




Figure 4: 2015 Regional exploration drilling program – plan view

PR15-1 For more information, contact Allan Candelario, CFA, Vice President of Investor Relations Phone: 1.866.365.4706 | E-mail: ir@rubiconminerals.com | www.rubiconminerals.com Rubicon Minerals Corporation | Suite 400–44 Victoria St. | Toronto, ON, CANADA M5C 1Y2 The Toronto Stock Exchange has not reviewed and does not accept responsibility for the adequacy or accuracy of this release