



Figure 1: Construction of the Santander mill and concentrate production facilities



Figure 2: Newly constructed Portal at Magistral Central deposit, Santander Mine, Peru




Figure 3: Underground development progress and plan on Magistral North, Central and South deposits at Santander Mine. Note presence of potentially significant satellite zone in the footwall to the Magistral North deposit.




Figure 4: Underground plan illustrating Channel sample locations on new footwall mineralized zone at Magistral North Deposit