Figure 2


North
South
*CEN235
*CEN218
CEN313
*CEN167
*CEN204
CEN443
*CEN283
CEN441
CEN388
*CEN163
Surface
Top of bedrock
350.0
300.0
250.0
200.0
150.0
100.0
50.0
73.2 m
*1.2 m @ 4.8% Cu
96.6 m
2.6 m @ 0.8% Cu
1.8 m @ 0.8% Cu
6.9 m @ 3.4% Cu
1.0 m @ 2.4% Cu
114.6 m
5.0 m @ 2.9% Cu
15.4 m @ 1.9% Cu
2.0 m @ 0.3% Cu
1.3 m @ 1.8% Cu
157 m
*42.6 m @ 1.0% Cu
145.7 m
3.8 m @ 0.5% Cu
29.0 m @ 2.5% Cu
7.5 m @ 1.6% Cu
157 m
*1.7 m @ 4.2% Cu
*3.7 m @ 2.1% Cu
*2.3 m @ 0.5% Cu
*8.1 m @ 0.6% Cu
*14.3 m @ 0.8% Cu
218.8 m
*1.5 m @ 0.2% Cu
*13.7 m @ 0.5% Cu
*3.5 m @ 2.1% Cu
252.4 m
264.9 m
*1.2 m @ 2.8 % Cu
3.6 m @ 1.6% Cu
4.5 m @ 0.4% Cu
10.4 m @ 1.8% Cu
3.0 m @ 0.2% Cu
294.7 m
*8.3 m @ 1.2% Cu
*3.9 m @ 0.6% Cu
*5.6 m @ 1.0% Cu
Highland cautions that it has not had the chance to verify the quality and accuracy of the historic sampling and drilling results reported for drill holes in dashed lines on this cross section, which predate the introduction on NI 43-101 and cautions readers not to rely upon them. The historic figures where generated from sources believed to be reliable, however, they have not been confirmed. Although the sampling and drilling results are relevant, they have not been verified.
Drill Intersections
0.20% Cu cutoff
Cross Section 600E
Looking East
Highland Copper Company Inc.
543S Deposit
Keweenaw County, MI
0
200
400
Feet
0
50
100
Meters
* Historic Homestake/Inco and Great Lakes Minerals Holes Dashed
* Denotes Non-Compliant Historical Assay Results