



Ferruginous Zone

(high iron – low nickel grades)

Limonite Zone

(high iron – medium nickel grades)

Saprolite Zone

(low iron-medium nickel grades)

Phase 1 DSO

Removes the overburden, giving access to saprolite feed for the Phase 2 processing plant

Phase 2 Processing Plant

Objective to process ore from lower limonite and saprolite zones and produce a mixed hydroxide product with 40% nickel content