

From TM-2016-756 - SEM/EDS analysis conducted at the CM2 for test #15



Image 2 – Example of a SEM-EDS Analysis results confirming 100% silicon<sup>6</sup>

<sup>6</sup> Detection limit of the SEM-EDS apparatus is 99.9% purity