



El Gallo Complex Development Photo Update

July 6, 2012



Crushing Plant Assembly

1 - Lime Silo

2 - Vibrating Screens

3 - 2nd & 3rd Stage Crushing

4 - Diesel Storage

5 - Primary Crusher



Installation of vibrating screens complete. Lime silo in background.



Final assembly of crushing plant nears completion.



Final assembly of crushing plant nears completion.



Final assembly of primary crusher.



Cone crusher assembly complete.



Installing final conveyors.



Finalizing ADR process plant.



Finalizing ADR process plant.



Finalizing ADR process plant.



Finalizing ADR process plant.



Overlooking the process plant and ponds.



Pre-stripping at Samaniego open pit continues.



Pre-stripping at Samaniego open pit continues.




Heap leach pad expansion nears completion.



Assay lab expansion.



Exploration core drilling at the Phase 1 production area.



For further information please contact:

Jenya Meshcheryakova

Investor Relations

Tel: (647) 258-0395 x 410

Toll Free: (866) 441-0690

Fax: (647) 258-0408

Email: info@mcewenmining.com