



Photo 1: Plant Overview – November 2010



Photo 2: Crushing and Grinding Circuit in Operation November 2010




Photo 3: Thickeners and Belt Filters – November 2010



Photo 4: Lucia Vein South Looking Southwest




Photo 5: Banded Colloform Texture at Lucia South Vein